
GARFIELD COUNTY

County Commissioners
D. Maloy Dodds
H. Dell LeFevre
Clare M. Ramsay
Camille A. Moore
Clerk/Auditor



55 South Main Street, P.O. Box 77 • Panguitch, Utah 84759 Phone (435) 676-8826 • Fax (435) 676-8239

Joe Thompson, Assessor
Judy Henrie, Treasurer
James D. Perkins, Sheriff
Barry L. Huntington, Attorney
A. Les Barker, Recorder
John W. Yardley,
Justice Court Judge

HAND DELIVERED

APR 0 4 2008

UTAH DIVISION OF SOLID & HAZARDOUS WASTE

08.01252

January 8, 2008

Mr. Dennis R. Downs, Director Utah Department of Environmental Quality Division of Solid and Hazardous Waste P.O. Box 144880 Salt Lake City, UT 84114-4880

Re: Annual Solid Waste Reports

Dear Dennis:

Enclosed are three annual reports required by the Solid and Hazardous Waste Control Board. The reports indicate the status of the landfills as of December 31, 2006.

If you have any questions, please contact me at (435) 676-1119. Thank you for your consideration.

Brian B. Bremner, P.E.

Garfield County Engineer

BBB:clq

Sincerely

enclosures

HAND DELIVERED

Mail to: Dennis R. Downs, Director Division of Solid and Hazardous Waste P.O. Box 144880 Salt Lake City, Utah 84114-4880

APR 0 4 2008

2008 SOLID WASTE LANDFILL ANNUAL REPORT & HAZARDOUS WASTE For Calendar year 2007 or most recent fiscal year

			(Please enter all the informat	ion requested below)			
cility Name:		TICABOO LANDFILL Facility Mailing Address: 55 S. MAIN ST., P.O. BOX 77					
	-	(Number & Street, Box and/or Route)					
				Zip Code: <u>89759</u>			
	C	County: <u>GARF</u>	IELD				
	Oumar						
	Owner N	Jame: GARFI	ELD COUNTY	Phone No.:(435) 676-1100			
			ss: <u>55 S. MAIN ST., P.</u>				
		,	(Number & Street, Box	and/or Route)	_		
	(ity: PANGUI	1CH, State: U1	Zip Code: <u>89759</u>	6 1110		
		Citle: Enginee		Phone No.:(435) 676	0-1119		
				x 77, Panguitch, UT 84759			
			l Address: engineer				
			ion only if the operator is not an em				
				Phone No.:(435) 676-1100			
	N	Mailing Addres	ss: 55 S. MAIN ST., P.	O. BOX 77 Street, Box and/or Route)			
	C	Contact's Name		Phone No.:(435) 676	6-1119		
		itle: Engine			×		
	C	Contact's Maili	ing Address: P.O. Box	x 77, Panguitch, UT 84759			
•	C	Contact's Emai	1 Address: engineer	@color-country.net			
173 - 174	787	/ 1.C.		· · · · · · · · · · · · · · · · · · ·		 .	
racilit	y Type a	nd Status					
	٦	☐ Class I	□ Class IIIb	□ Class V			
		X Class II	□ Class IVa	□ Class VI			
		☐ Class IIIa	□ Class IVb				
				/D) cell as part of the permit (not	operated u	nder a	
	separate p	ermit number)?	Yes N	No X year enter date closed:			
	11 lacility	y was permane	may closed during the y	ear enter date crosed.			
	Annual	Disposal		,			
L							
		ns received at	facility for disposal:	1592 cubic yards			
Waste T	ype	* *	Waste Origin	Total		uremen	
		In-State	Out-of-State	;	Tons	Cubic Yards	
	oal 1	592				. 🛭	
Municip	-	,			. 🗖	⊠	
-	a1 0	\				160	
Municip Industria	al <u>0</u>	<u>)</u>	•	· ·		₩	

Conversion Factor Used			
x No conversion factors used ☐ Conversion factor from rules (R315-302-2(4)) ☐ Site specific conversion used Please list:		1	· · · · · · · · · · · · · · · · · · ·
Recycling			
Tons Recycled: N/A (Should not be included in the tons or cubic yards (please circle correct un Compost should be reported on separate form.)	its) disposed above	also excludes wa	Tons/Cubic Yds ste diverted to compost.
Jtah Disposal Fee			
Disposal Fee Required Yes ☑ No □	Fee Type Per Ton	□ Annual	
Disposal Fee Paid			•
Municipal \$16.00/yd	C/D	<u>\$</u>	
Industrial <u>\$</u>	Annual	<u>\$</u>	
inancial Assurance			
Current Closure Cost Estimate: Current Post-Closure Cost Estimate:			
Current Financial Assurance Mechanism: (ie. Bond, Trust Fund, Corporate or government Test etc.)	Escro	w Account	
Financial Assurance Mechanism Holder:			
Other Required Reports			
Financial Assurance: Each facility must recalculate the confining inflation and design changes each year. The recalculation, fully covered by the assurance mechanism currently be util a trust account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account for the should include a copy of the most recent account should include a copy of the most recent account for the should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should include a copy of the most recent account should be	along with proc ized, must be su count statement.	of that the new bmitted. Fac	w cost estimates are cilities that are using
Ground Water Monitoring: Each facility that is required to water monitoring report that contains water elevations, sam			
box if facility is <u>exempt</u> from ground water monitoring X <u>Explosive Gas Monitoring</u> : A gas monitoring report must be that has receive an exemption, a Class III, IV, or VI landfil	be included unle	ss the facility acility that ha	is a Class II landfill as an exemption.
Check box if facility is exempt from gas monitoring X Training Report: A report of all training program	ıs or procedu	es complet	ed by facility
personnel during the year. Signature: ignature should be by an executive officer, general partner, proprietor, elected officing	al, or a duly authoriz		e. A duly authorized
epresentative must meet the requirements of the solid waste rules (UAC R315-310-2	(4)(d)).		

FINANCIAL ASSURANCE

An updated cost estimate is attached.

GROUNDWATER MONITORING REPORT:

No groundwater wells exist at this facility, and no activities have been performed.

GAS MONITORING REPORT:

No landfill gas monitoring was conducted at the Ticaboo Landfill during 2007. Garfield County initiated a modified gas detection program at the Ticaboo Landfill as part of its permit renewal process.

TRAINING PROGRAM REPORT:

Two of the Landfill operators had completed MOLO Training prior to December 31, 2004.